


AT88SC0204 resetter by GenaAlfa Recommended schematic with PIC18F2550

<http://igoruha.org/at88resetter.php>




If all components is correct, then works immediately, if have problems with OTP zone of Xerox01, then check diagramme at point A

Test Condition:

- 1.Xerox01 chip is connected
- 2.Select "Erase Xerox01 OTP" (free version) or Press "Programm Xerox01" (paid version)

Only 8 impulsess will be present at one time.



Schematic with PIC18F4550 is not recommended, but works

AT88SC0204 resetter by GenaAlfa

<http://igoruha.org/at88resetter.php>

